

SREEPADMAM FIRE ENGINEERING


FIRE & LIFE SAFETY ENGINEERS

II/ 467A, Avinissery, Thrissur, Kerala, PIN 680 306. www.sreefireprotection.in
e-mail: fire4435@gmail.com Phone: +91 487-2353581, +91 949675 4435
TIN:32080675195, CST:32080675195C, GSTIN:32AXKPP3407D1ZT

Location Sheet of Fire Extinguishers

Owner : Amala Cancer Hospital Society, Amala nagar
Location : Amala Cancer Hospital Society, Amala nagar
Date: 13/12/2025


SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
1	1	5kg	ABC,DCP	st.marys	ordinary lift machine room	2012	13/12/2024	12/12/2025	Refilled OK
2	2	5kg	ABC,DCP	st.marys	cardiology lift machine room	2012	09/12/2024	08/12/2025	Checked OK
3	3	5kg	ABC,DCP	st.marys	causality lift machine room	2012	09/12/2024	08/12/2025	Checked OK
4	4	4 KG	ABC	sacred heart	8th floor corridor	2024	10/12/2024	09/12/2025	Refilled OK
5	5	9L	A,WATER	st.marys	9th floor causality lift stair	2007	09/12/2024	08/12/2025	Checked OK
6	6	4KG	ABC	sacred heart	8th floor corridor	2024	10/12/2024	09/12/2025	Checked OK
7	7	10kg	BC,DP	st.marys	8th floor causality lift stair	1991	09/12/2024	08/12/2025	Checked OK
8	8	4KG	ABC	sacred heart	8th floor corridor	2024	10/12/2024	09/12/2025	Checked OK
9	9	4KG	ABC	st.marys	Insurance first floor	2023	09/12/2024	08/12/2025	Checked OK
10	10	4KG	ABC	sacred heart	7th floor corridor	2024	10/12/2024	09/12/2025	Checked OK




SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
11	11	4KG	ABC	sacred heart	7th floor corridor	2024	10/12/2024	09/12/2025	Checked OK
12	12	10kg	BC,DP	st.marys	5th floor causality lift stair	2007	09/12/2024	08/12/2025	Checked OK
13	13	10 kg	BC,DP	st.marys	6 th floor stair	2007	09/12/2024	08/12/2025	Checked OK
14	14	10kg	BC,DP	st.marys	7th floor causality lift stair	2008	9/12/2024	08/12/2025	Checked OK
15	15	4KG	ABC	sacred heart	7th floor corridor	2024	10/12/2024	09/12/2025	Checked OK
16	16	10kg	BC,DP	st.marys	4th floor causality lift stair	2007	09/12/2024	08/12/2025	Checked OK
17	17	10kg	BC,DP	st.marys	3rd floor causality lift stair	2007	09/12/2024	08/12/2025	Checked OK
18	18	5kg	BC,DP	sacred heart	6th floor corridor	2007	10/12/2024	09/12/2025	Checked OK
19	19	5kg	BC,DP	st.marys	2nd floor casualty lift stair	2004	09/12/2024	08/12/2025	Checked OK
20	20	5kg	BC,DP	sacred heart	6th floor corridor	2004	10/12/2024	09/12/2025	Checked OK
21	22	5kg	BC,DP	sacred heart	6th floor corridor	2013	10/12/2024	09/12/2025	Checked OK
22	23	5kg	ABC,DCP	st.marys	basement floor electrical room	2008	09/12/2024	08/12/2025	Checked OK
23	24	2kg	CO2	st.marys	basement floor x-ray waiting area	2013	09/12/2024	08/12/2025	Checked OK
24	25	2kg	CO2	st.marys	basement floor outside pet scan	2013	09/12/2024	08/12/2025	Checked OK
25	26	5kg	BC,DP	st.marys	basement floor MRI equipment room	2009	09/12/2024	08/12/2025	Checked OK
26	27	2kg	CO2	st.marys	1st floor outside x-ray room	2013	09/12/2024	08/12/2025	Checked OK
27	28	4kg	ABC,DCP	Chavara	Lift machine room		10/12/2024	09/12/2025	Checked OK
28	29	5kg	ABC,DCP	Chavara	1st floor main veranda, ward-9	2010	11/12/2024	10/12/2025	Checked OK
29	30	5kg	ABC,DCP	Chavara	1st floor main veranda, ward-11	2012	11/12/2024	10/12/2025	Checked OK

SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
30	31	5kg	ABC,DCP	Chavara	1st floor main veranda, ward-12	2012	11/12/2024	10/12/2025	Checked OK
31	32	5kg	ABC,DCP	Chavara	1st floor main veranda, ward-14	2008	11/12/2024	10/12/2025	Checked OK
32	33	5kg	ABC,DCP	Chavara	1st floor way to st.mary's block	2008	11/12/2024	10/12/2025	Checked OK
33	34	5kg	ABC,DCP	Chavara	1st floor main veranda, ward-16	2012	11/12/2024	10/12/2025	Checked OK
34	35	5kg	ABC,DCP	Chavara	1st floor gastrology dept.	2012	11/12/2024	10/12/2025	Checked OK
35	36	5kg	ABC,DCP	Chavara	1st floor main veranda, ward-18	2008	11/12/2024	10/12/2025	Checked OK
36	37	5kg	BC	Chavara	Infectons: diseases department		11/12/2024	10/12/2025	Checked OK
37	38	4kg	ABC	st.marys	Outside emergency		09/12/2024	08/12/2025	Checked OK
38	39	5kg	ABC,DCP	Chavara	Geriyathic medicine corridor	2012	11/12/2024	10/12/2025	Checked OK
39	40	5kg	ABC	Chavara	Ground floor- Ward 6		13/12/2024	12/12/2025	Refilled OK
40	41	5kg	ABC,DCP	Chavara	Ground floor main veranda ward-4	2012	11/12/2024	10/12/2025	Checked OK
41	43	5kg	ABC,DCP	Chavara	ground floor OT	2012	11/12/2024	10/12/2025	Checked OK
42	44	5kg	ABC,DCP	Chavara	ground floor main veranda, ward-4	2012	11/12/2024	10/12/2025	Checked OK
43	45	5kg	ABC,DCP	Chavara	ground floor main veranda, Chapel	2012	11/12/2024	10/12/2025	Checked OK
44	46	5kg	ABC	Chavara	ground floor- Out side ward-3	2012	11/12/2024	10/12/2025	Checked OK
45	47	5kg	ABC,DCP	Chavara	ground floor main veranda, ward-2	2012	11/12/2024	10/12/2025	Checked OK
46	48	5kg	ABC	Chavara	Ground floor- Labour room (Front)		11/12/2024	10/12/2025	Checked OK
47	49	2kg	CO2	Chavara	2 nd floor- mrd	2009	11/12/2024	10/12/2025	Checked OK
48	51	2kg	CO2	sacred heart	Ground floor waiting area radition oncology	2008	10/12/2024	09/12/2025	Checked OK


SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
49	52	5kg	ABC,DCP	sacred heart	lift machine room	2012	13/12/2024	12/12/2025	Refilled OK
50	53	5kg	ABC,DCP	sacred heart	4th floor ward 94 (female side)	2012	10/12/2024	09/12/2025	Checked OK
51	54	5kg	ABC,DCP	sacred heart	inside pump room	2012	10/12/2024	09/12/2025	Checked OK
52	55	2kg	CO2	sacred heart	ground floor near lift	2013	10/12/2024	09/12/2025	Checked OK
53	56	5kg	ABC,DCP	st.marys	terrace hall	2011	09/12/2024	08/12/2025	Checked OK
54	57	5kg	ABC,DCP	Chavara	OT cone lift room		10/12/2024	09/12/2025	Checked OK
55	58	5kg	ABC,DCP	st.marys	generator room		12/12/2024	11/12/2025	Checked OK
56	59	5kg	BC,DP	others	Panel board room ward 1	2004	12/12/2024	11/12/2025	Checked OK
57	60	9L	foam	others	diesel room		12/12/2024	11/12/2025	Checked OK
58	61	2kg	CO2	st.marys	Pneumatic new room		12/12/2024	11/12/2025	Checked OK
59	62	5kg	BC,DP	others	transformer room		12/12/2024	11/12/2025	Checked OK
60	63	5kg	BC,DP	chavara	generator room panel board room	2009	12/12/2024	11/12/2025	Checked OK
61	64	5kg	BC,DP	chavara	generator room panel board room	2004	12/12/2024	11/12/2025	Checked OK
62	65	5kg	BC,DP	chavara	generator room panel board room	2009	12/12/2024	11/12/2025	Checked OK
63	66	5kg	BC,DP	Chavara	transformer room	2004	12/12/2024	11/12/2025	Checked OK
64	67	9L	foam	chavara	diesel room	2009	12/12/2024	11/12/2025	Checked OK
65	68	5kg	BC,DP	chavara	HT pane room	2008	12/12/2024	11/12/2025	Checked OK
66	69	5kg	BC,DP	chavara	HT pane room	2008	12/12/2024	11/12/2025	Checked OK
67	70	4kg	ABC,DCP	Others	transformer room for St.mary's		12/12/2024	11/12/2025	Checked OK




SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
68	72	5kg	ABC,DCP	others	generator room	2009	12/12/2024	11/12/2025	Checked OK
69	73	9L	FOAM	sh / others	sh diesel room		09/12/2024	08/12/2025	Checked OK
70	74	5kg	BC,DP	others	panel board SSB 6E		12/12/2024	11/12/2025	Checked OK
71	75	2kg	CO2	chavara	ground floor pharmacy	2012	11/12/2024	10/12/2025	Checked OK
72	76	5kg	BC,DP	chavara	second floor MRD	2008	11/12/2024	10/12/2025	Checked OK
73	77	5kg	ABC,DP	chavara	Microbiology Lab		11/12/2024	10/12/2025	Checked OK
74	78	4kg	ABC	chavara	1st floor ward 9A	2015	11/12/2024	10/12/2025	Checked OK
75	79	4kg	ABC	Chavara	Ground floor- Ward 1(Nursing station)		11/12/2024	10/12/2025	Checked OK
76	80	5kg	BC,DP	chavara	first floor central store		11/12/2024	10/12/2025	Checked OK
77	81	2kg	CO2	sh	mrd 3 ed floor	2014	09/12/2024	08/12/2025	Checked OK
78	82	5kg	ABC	Chavara	Ground floor- OT		11/12/2024	10/12/2025	Checked OK
79	84	2kg	CO2	st.marys	Pneumatic new room		09/12/2024	08/12/2025	Checked OK
80	85	2kg	CO2	st.marys	Pneumatic new room		09/12/2024	08/12/2025	Checked OK
81	86	2kg	CO2	st.marys	Biochemistry new room		09/12/2024	08/12/2025	Checked OK
82	87	2kg	CO2	st.marys	Biochemistry UPS room		09/12/2024	08/12/2025	Checked OK
83	89	4kg	ABC	Chavara	2nd floor mrd		11/12/2024	10/12/2025	Checked OK
84	90	4kg	ABC	Chavara	2nd floor mrd (opposite lift)		11/12/2024	10/12/2025	Checked OK
85	91	2kg	CO2	Chavara	2nd floor biomedical engineering		11/12/2024	10/12/2025	Checked OK
86	92	4kg	ABC	Chavara	1st floor administrative office	2022	11/12/2024	10/12/2025	Checked OK




SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
87	93	4kg	ABC	Chavara	2nd floor HR department	2022	11/12/2024	10/12/2025	Checked OK
88	94	4kg	ABC	Chavara	1st floor ward 16		11/12/2024	10/12/2025	Checked OK
89	95	4kg	ABC	Chavara	Ground floor ward 7		11/12/2024	10/12/2025	Checked OK
90	96	5kg	ABC	Chavara	Ground floor corridor (near ward 5)		11/12/2024	10/12/2025	Checked OK
91	97	4kg	ABC	Chavara	Ground floor- Surgery OP		11/12/2024	10/12/2025	Checked OK
92	98	2kg	CO2	sacred heart	Basement floor		10/12/2024	09/12/2025	Checked OK
93	100	4kg	ABC	sacred heart	3rd floor- Left side corridor		10/12/2024	09/12/2025	Checked OK
94	101	2kg	BC,DP	sacred heart	basement floor electrical room	2014	10/12/2024	09/12/2025	Checked OK
95	102	2kg	CO2	sacred heart	Canteen (Amala café)		09/12/2024	08/12/2025	Checked OK
96	103	5kg	ABC,DCP	st.marys	9th floor electrical room	2012	09/12/2024	08/12/2025	Checked OK
97	104	5kg	ABC,DCP	st.marys	8th floor electrical room	2012	09/12/2024	8/12/2025	Checked OK
98	105	5kg	ABC,DCP	st.marys	7th floor electrical room	2012	09/12/2024	8/12/2025	Checked OK
99	106	5kg	ABC,DCP	st.marys	6th floor electrical room	2012	09/12/2024	08/12/2025	Checked OK
100	107	5kg	ABC,DCP	st.marys	5th floor electrical room	2012	13/12/2024	12/12/2025	Refilled OK
101	108	5kg	ABC,DCP	st.marys	4th floor electrical room	2012	09/12/2024	08/12/2025	Checked OK
102	109	5kg	ABC,DCP	st.marys	3rd floor electrical room	2012	09/12/2024	08/12/2025	Checked OK
103	110	5kg	ABC,DCP	st.marys	2nd floor electrical room	2012	09/12/2024	08/12/2025	Checked OK
104	111	5kg	ABC,DCP	st.marys	1st floor electrical room	2012	13/12/2024	12/12/2025	Refilled OK
105	112	5kg	ABC,DCP	medical collage	lift machine room		09/12/2024	08/12/2025	Checked OK




SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
106	113	4kg	ABC	Bsc new block	3rd floor near fire station		10/12/2024	09/12/2025	Refilled OK
107	114	4kg	ABC	Bsc new block	2nd floor near fire station		10/12/2024	09/12/2025	Checked OK
108	115	4kg	ABC	Bsc new block	1st floor near fire station		10/12/2024	09/12/2025	Checked OK
109	116	4kg	ABC	Bsc old block	Terrace floor		12/12/2024	11/12/2025	Checked OK
110	117	4kg	ABC	Bsc new block	Ground floor near fire station		10/12/2024	09/12/2025	Checked OK
111	118	2kg	CO2	st.marys	1st floor pharmacy	2012	09/12/2024	08/12/2025	Checked OK
112	119	2kg	CO2	Chavara	store	2010	11/12/2024	10/12/2025	Checked OK
113	120	2kg	CO2	st.marys	2 nd floor - Pathology	2010	11/12/2024	10/12/2025	Checked OK
114	121	5kg	BC,DP	st.marys	Basement floor ordinary lift stair	2011	09/12/2024	08/12/2025	Checked OK
115	122	5kg	BC,DP	st.marys	basement floor electrical room	2009	09/12/2024	08/12/2025	Checked OK
116	123	4kg	ABC	Annex	8th floor near fire station		10/12/2024	09/12/2025	Checked OK
117	124	4kg	ABC,DCP	st.marys	2nd floor ortho OP	2015	09/12/2024	08/12/2025	Checked OK
118	125	4kg	ABC,DCP	st.marys	2nd floor outside central lecture hall	2015	09/12/2024	08/12/2025	Checked OK
119	126	4kg	ABC,DCP	st.marys	3rd floor ward 31	2015	09/12/2024	08/12/2025	Checked OK
120	127	4kg	ABC,DCP	st.marys	3rd floor ward 30	2015	09/12/2024	08/12/2025	Checked OK
121	128	4kg	ABC,DCP	st.marys	5th floor ward 39	2015	09/12/2024	08/12/2025	Checked OK
122	129	4kg	ABC,DCP	st.marys	3rd floor ENT OP	2015	09/12/2024	08/12/2025	Checked OK
123	130	4kg	ABC,DCP	st.marys	4th floor ward 33	2015	09/12/2024	08/12/2025	Checked OK
124	131	4 kg	ABC,DCP	st.marys	4 th floor ward 34	2015	09/12/2024	08/12/2025	Checked OK




SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
125	132	4 kg	ABC,DCP	st.marys	4th floor ward 35	2015	09/12/2024	08/12/2025	Checked OK
126	133	4kg	ABC,DCP	st.marys	5th floor ward 38	2015	09/12/2024	08/12/2025	Checked OK
127	134	4kg	ABC,DCP	st.marys	3rd floor ophthalmology	2018	09/12/2024	08/12/2025	Checked OK
128	135	4kg	ABC,DCP	st.marys	5th floor ward 40	2015	09/12/2024	08/12/2025	Checked OK
129	136	4kg	ABC,DCP	st.marys	5th floor ward 36	2015	09/12/2024	08/12/2025	Checked OK
130	137	4kg	ABC,DCP	chavara	ground floor OT infront	2007	11/12/2024	10/12/2025	Checked OK
131	138	4kg	ABC,DCP	st.marys	6 th floor RICU	2015	09/12/2024	08/12/2025	Checked OK
132	139	4kg	ABC,DCP	st.marys	6th floor CCU infront	2015	09/12/2024	08/12/2025	Checked OK
133	140	2 KG	CO2	st.marys	6 th floor near micu	2014	09/12/2024	08/12/2025	Checked OK
134	141	2 kg	CO2	st.marys	7 th floor cicu	2014	09/12/2024	08/12/2025	Checked OK
135	142	2KG	CO2	st.marys	7th floor CVSICU	2014	09/12/2024	08/12/2025	Checked OK
136	143	2KG	CO2	st.marys	7th floor outside cardiac OT	2014	09/12/2024	08/12/2025	Checked OK
137	144	4kg	ABC,DCP	st.marys	8th floor ward 50 near passagw	2015	09/12/2024	08/12/2025	Checked OK
138	145	4kg	ABC,DCP	st.marys	8th floor ward 50	2015	09/12/2024	08/12/2025	Checked OK
139	146	4kg	ABC,DCP	st.marys	8th floor ward 50	2015	09/12/2024	08/12/2025	Checked OK
140	147	4kg	ABC,DCP	st.marys	8th floor ward 50	2015	09/12/2024	08/12/2025	Checked OK
141	148	2kg	CO2	st.marys	9th floor dialysis	2014	09/12/2024	08/12/2025	Checked OK
142	149	4kg	ABC,DCP	st.marys	9th floor ward 60C	2015	09/12/2024	08/12/2025	Checked OK
143	150	4kg	ABC,DCP	st.marys	9th floor ward 60B	2015	09/12/2024	08/12/2025	Checked OK




SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
144	151	4kg	ABC,DCP	st.marys	9th floor ward 60	2015	13/12/2024	12/12/2025	Refilled OK
145	152	2kg	CO2	sacred heart	ground floor x-ray out side	2014	10/12/2024	09/12/2025	Checked OK
146	154	2kg	CO2	sacred heart	1st floor cssd	2004	10/12/2024	09/12/2025	Checked OK
147	155	4kg	ABC,DCP	sacred heart	1st floor OP waiting area	2015	10/12/2024	09/12/2025	Checked OK
148	156	4kg	ABC,DCP	sacred heart	1st floor opposite staff lift	2015	10/12/2024	09/12/2025	Checked OK
149	157	4kg	ABC,DCP	sacred heart	2nd floor ICU waiting area	2015	10/12/2024	09/12/2025	Checked OK
150	158	2kg	CO2	sacred heart	2nd floor SSICU	2014	10/12/2024	09/12/2025	Checked OK
151	159	2kg	CO2	sacred heart	2nd floor OT nursing station	2014	10/12/2024	09/12/2025	Checked OK
152	160	2kg	CO2	sacred heart	2nd floor near male changing room	2014	10/12/2024	09/12/2025	Checked OK
153	161	2kg	CO2	sacred heart	basement floor CT waiting area	2012	10/12/2024	09/12/2025	Checked OK
154	162	9L	foam	others	diesel room- Ayurveda	2011	12/12/2024	11/12/2025	Checked OK
155	163	5kg	BC,DP	others	generator room- Ayurveda	2004	12/12/2024	11/12/2025	Checked OK
156	164	5kg	BC,DP	others	Panel board room- Ayurveda	2009	12/12/2024	11/12/2025	Checked OK
157	165	5kg	BC,DP	others	transformer room- Ayurveda	2009	12/12/2024	11/12/2025	Checked OK
158	166	5kg	BC,DP	others	transformer room- Ayurveda	2008	12/12/2024	11/12/2025	Checked OK
159	167	2kg	CO2	st.marys	basement floor CT waiting area	2004	9/12/2024	8/12/2025	Checked OK
160	168	2kg	CO2	Chavara	maintanance	2014	11/12/2024	10/12/2025	Checked OK
161	169	10kg	BC,DP	others	liquid oxygen plant		12/12/2024	11/12/2025	Checked OK
162	171	2kg	CO2	sacred heart	5th floor OT waiting area	2014	10/12/2024	9/12/2025	Checked OK




SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
163	172	5kg	BC,DP	sacred heart	5th floor dermatology OP	2004	10/12/2024	9/12/2025	Checked OK
164	173	5kg	BC,DP	sacred heart	5th floor pharmacy outside	2004	10/12/2024	9/12/2025	Checked OK
165	174	5kg	BC,DP	sacred heart	4 th floor	2003	10/12/2024	9/12/2025	Checked OK
166	175	5kg	BC,DP	sacred heart	4th floor ward 94 right side	2004	10/12/2024	9/12/2025	Checked OK
167	176	5kg	BC,DP	sacred heart	inside fire pump room	2004	10/12/2024	9/12/2025	Checked OK
168	177	4kg	ABC	Annex	8th floor near lift		10/12/2024	9/12/2025	Checked OK
169	178	4kg	ABC,DCP	chavara	2nd floor veranda ward 22	2018	11/12/2024	10/12/2025	Checked OK
170	179	5kg	BC,DP	chavara	2nd floor veranda ward 23	2004	11/12/2024	10/12/2025	Checked OK
171	180	4kg	ABC,DCP	chavara	2nd floor veranda ward 24	2015	13/12/2024	12/12/2025	Refilled OK
172	181	4kg	ABC	Annex	7th floor near fire station		10/12/2024	09/12/2025	Checked OK
173	182	4kg	ABC	bsc	4 th floor terrace	2015	13/12/2024	12/12/2025	Refilled OK
174	183	5kg	BC,DP	others	baby care	2009	12/12/2024	11/12/2025	Checked OK
175	184	5kg	BC,DP	others	baby care	2009	12/12/2024	11/12/2025	Checked OK
176	185	5kg	BC,DP	others	chaithanya	2009	12/12/2024	11/12/2025	Checked OK
177	186	5kg	BC,DP	annex	MRD- Basement	2004	10/12/2024	09/12/2025	Checked OK
178	187	5kg	BC	annex	Terrace lift machine room		10/12/2024	09/12/2025	Checked OK
179	188	5kg	BC	others	mens hostel electrical room		12/12/2024	11/12/2025	Checked OK
180	189	5kg	BC,DP	others	waste plant	2004	12/12/2024	11/12/2025	Checked OK
181	190	5kg	BC,DP	bsc	B.sc college third floor, corridor	2004	10/12/2024	9/12/2025	Checked OK




SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
182	191	2kg	CO2	chavara	Microbio ogy		11/12/2024	10/12/2025	Checked OK
183	192	2kg	CO2	chavara	Ground floor- Post operative ICU (Ward 5)		11/12/2024	10/12/2025	Checked OK
184	193	4 kg	clean agent	st marys	Basement- Observation room MRI	2024	09/12/2024	08/12/2025	Checked OK
185	194	2kg	CO2	Chavara	ground floor bmo	2015	11/12/2024	10/12/2025	Checked OK
186	195	2kg	CO2	chavara	blood bank	2012	11/12/2024	10/12/2025	Checked OK
187	196	2kg	CO2	chavara	near SICU	2015	11/12/2024	10/12/2025	Checked OK
188	197	2kg	CO2	chavara	1st floor infront OT	2012	11/12/2024	10/12/2025	Checked OK
189	198	2kg	CO2	chavara	infront PICU	2015	11/12/2024	10/12/2025	Checked OK
190	199	2kg	CO2	chavara	near NICU	2015	11/12/2024	10/12/2025	Checked OK
191	200	2kg	CO2	st marys	ENT OP	2015	09/12/2024	08/12/2025	Checked OK
192	201	4 kg	ABC,DCP	st marys	9th floor	2018	09/12/2024	08/12/2025	Checked OK
193	202	4 kg	ABC,DCP	st marys	8th floor near fire station	2018	09/12/2024	08/12/2025	Checked OK
194	203	4 kg	ABC,DCP	st marys	7 th floor fire station	2018	09/12/2024	08/12/2025	Checked OK
195	204	4 kg	ABC,DCP	st marys	6th floor near fire station	2018	09/12/2024	08/12/2025	Checked OK
196	205	4 kg	ABC	st marys	5th floor near fire station		09/12/2024	08/12/2025	Checked OK
197	206	4 kg	ABC,DCP	st marys	4th floor near fire station	2018	13/12/2024	12/12/2025	Refilled OK
198	207	4 kg	ABC,DCP	st marys	near fire station- 3rd floor	2018	09/12/2024	08/12/2025	Checked OK
199	208	4 kg	ABC,DCP	st marys	2nd floor near fire station	2018	09/12/2024	08/12/2025	Checked OK
200	209	4 kg	ABC,DCP	st marys	1st floor near fire station	2018	09/12/2024	08/12/2025	Checked OK



SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
201	210	2kg	CO2	st marys	Basement floor- CT observation		09/12/2024	08/12/2025	Checked OK
202	211	2kg	CO2	sacred heart	near chiller plant	2018	09/12/2024	08/12/2025	Checked OK
203	212	4 kg	ABC,DCP	others	Generator room- SH	2018	12/12/2024	11/12/2025	Checked OK
204	213	4 kg	ABC,DCP	others	Generator room- SH	2018	12/12/2024	11/12/2025	Checked OK
205	214	4 kg	ABC,DCP	st.marys	Generator room- SH	2018	12/12/2024	11/12/2025	Checked OK
206	215	4 kg	ABC,DCP	others	Generator room- SH	2018	12/12/2024	11/12/2025	Checked OK
207	217	5kg	BC,DP	devamatha	electrical room	2011	12/12/2024	11/12/2025	Checked OK
208	218	2kg	CO2	chavara	centralised laundry	2018	11/12/2024	10/12/2025	Checked OK
209	219	5kg	ABC,DCP	chavara	centralised laundry	2018	11/12/2024	10/12/2025	Checked OK
210	220	5kg	ABC,DCP	chavara	Panel room- Laundry	2018	11/12/2024	10/12/2025	Checked OK
211	221	4kg	ABC	Annex	7th floor near lift		10/12/2024	09/12/2025	Checked OK
212	222	4kg	ABC,DCP	Auditorium	Auditorium main hall		10/12/2024	09/12/2025	Checked OK
213	223	4kg	ABC	Annex	6th floor near fire station		10/12/2024	09/12/2025	Checked OK
214	224	4kg	ABC	Annex	6th floor near lift		10/12/2024	09/12/2025	Checked OK
215	225	4kg	ABC	Bsc	Bsc third floor near lift		10/12/2024	09/12/2025	Checked OK
216	226	4kg	ABC	Bsc	Bsc third floor near fire station		10/12/2024	09/12/2025	Checked OK
217	227	4kg	ABC	Bsc	2nd floor near lift		10/12/2024	09/12/2025	Checked OK
218	228	4kg	ABC	Bsc	2nd floor near fire station		10/12/2024	09/12/2025	Checked OK
219	229	4kg	ABC	Bsc	1st floor near lift		10/12/2024	09/12/2025	Checked OK




SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
220	230	4kg	ABC	Bsc	1st floor near fire station		10/12/2024	09/12/2025	Checked OK
221	231	4kg	ABC	Bsc	Ground floor near fire station		10/12/2024	09/12/2025	Checked OK
222	232	4kg	ABC	Bsc	Ground floor near fire station		10/12/2024	09/12/2025	Checked OK
223	233	4kg	ABC	Annex	5th floor near lift		10/12/2024	09/12/2025	Checked OK
224	234	4kg	ABC,DCP	Auditorium	Auditorium main hall		10/12/2024	09/12/2025	Checked OK
225	235	5kg	BC,DP	chavara	Store	2008	11/12/2024	10/12/2025	Checked OK
226	236	5 kg	ABC	St.marys	9 th floor electrical room		09/12/2024	08/12/2025	Checked OK
227	238	2 kg	co2	chavara	store	2008	11/12/2024	10/12/2025	Checked OK
228	239	2 kg	co2	cancer centre	research centre		13/12/2024	12/12/2025	Refilled OK
229	240	2 kg	co2	cancer centre	research centre first floor		12/12/2024	11/12/2025	Checked OK
230	241	4kg	ABC	cancer centre	research centre ground floor		12/12/2024	11/12/2025	Checked OK
231	242	4kg	ABC	cancer centre	research centre first floor		12/12/2024	11/12/2025	Checked OK
232	243	4 kg	ABC	Bsc	electrical room ground floor		10/12/2024	9/12/2025	Checked OK
233	244	4 kg	ABC	medical college	ground floor		09/12/2024	08/12/2025	Checked OK
234	245	4 kg	ABC	medical college	first floor		09/12/2024	08/12/2025	Checked OK
235	246	4 kg	ABC	medical college	second floor		09/12/2024	08/12/2025	Checked OK
236	247	4 kg	ABC	medical college	third floor		09/12/2024	08/12/2025	Checked OK
237	248	2 kg	co2	St.marys	second floor centre lab		09/12/2024	08/12/2025	Checked OK
238	249	2 kg	co2	St.marys	near observation unit green area		09/12/2024	08/12/2025	Checked OK



SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
239	250	4kg	ABC,DCP	sacred heart	basement floor		10/12/2024	9/12/2025	Checked OK
240	251	2kg	CO2	Auditorium	Auditorium electric room		10/12/2024	9/12/2025	Checked OK
241	252	2kg	CO2	Auditorium	Auditorium main hall		10/12/2024	9/12/2025	Checked OK
242	253	2kg	CO2	Auditorium	Auditorium mainhall		10/12/2024	9/12/2025	Checked OK
243	254	4 kg	ABC	Auditorium	Auditorium main hall		10/12/2024	9/12/2025	Checked OK
244	255	2kg	CO2	Annex	5 th floor near fire station		10/12/2024	9/12/2025	Checked OK
245	256	4kg	ABC	Annex	4th floor near lift		10/12/2024	9/12/2025	Checked OK
246	257	4kg	ABC	Annex	4th floor near fire station		10/12/2024	9/12/2025	Checked OK
247	258	4kg	ABC	chavara	Ground floor- Ward 6 (Nursing station)		11/12/2024	10/12/2025	Checked OK
248	259	5kg	ABC, DCP	chavara	Mourtuary outside		10/12/2024	9/12/2025	Checked OK
249	260	4kg	ABC,DCP	Devamatha Annex	Lift machine room		10/12/2024	9/12/2025	Checked OK
250	261	4kg	ABC	St marys	Terrace floor (Rain water treatment plant)		11/12/2024	10/12/2025	Checked OK
251	262	2kg	CO2	St marys	Terrace floor		09/12/2024	08/12/2025	Checked OK
252	263	4kg	ABC	St marys	second floor pathology lab		09/12/2024	08/12/2025	Checked OK
253	264	4kg	ABC	Psychiatry	Near waiting area		12/12/2024	11/12/2025	Checked OK
254	265	4kg	ABC	Annex	3rd floor near fire station		10/12/2024	9/12/2025	Checked OK
255	266	4kg	ABC	Annex	3rd floor near lift		10/12/2024	9/12/2025	Checked OK
256	267	4kg	ABC	Annex	2nd floor near lift		11/12/2024	10/12/2025	Checked OK
257	268	4kg	ABC	Annex	2nd floor near fire station		10/12/2024	9/12/2025	Checked OK
258	269	4kg	ABC	Annex	1st floor near lift		10/12/2024	9/12/2025	Checked OK
259	270	4kg	ABC	Annex	Ground floor near lift		13/12/2024	12/12/2025	Refilled OK




SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
260	271	4kg	ABC	St.Joseph	6th floor- Front side fire station		13/12/2024	12/12/2025	Refilled OK
261	272	4kg	ABC	St.Joseph	6th floor- Back side fire station		09/12/2024	08/12/2025	Checked OK
262	273	4kg	ABC	chavara	Store		13/12/2024	12/12/2025	Refilled OK
263	274	4kg	ABC	St.Joseph	5th floor- Front side fire station		09/12/2024	08/12/2025	Checked OK
264	276	4kg	ABC	St.Joseph	4th floor- Front side fire station		09/12/2024	08/12/2025	Checked OK
265	277	4kg	ABC	St.Joseph	3rd floor back side fire station		09/12/2024	08/12/2025	Checked OK
266	278	4kg	ABC	St.Joseph	3rd floor- Front side near fire station		09/12/2024	08/12/2025	Checked OK
267	280	4kg	ABC	St.Joseph	2nd floor- Front side fire station		09/12/2024	08/12/2025	Checked OK
268	281	4kg	ABC	St.Joseph	2nd floor- Back side fire station		09/12/2024	08/12/2025	Checked OK
269	282	4kg	ABC	St.Joseph	1st floor- Front side fire station		09/12/2024	08/12/2025	Checked OK
270	283	4kg	ABC	St.Joseph	1st floor- Back side fire station		09/12/2024	08/12/2025	Checked OK
271	284	4kg	ABC	St.Joseph	Ground floor- Front side fire station		09/12/2024	08/12/2025	Checked OK
272	285	4kg	ABC	St.Joseph	Ground floor- Back side fire station		09/12/2024	08/12/2025	Checked OK
273	286	4kg	ABC	St.Joseph	1st floor- Front side fire station		09/12/2024	08/12/2025	Checked OK
274	287	4kg	ABC	St.Joseph	electrical room		09/12/2024	08/12/2025	Checked OK
275	288	4kg	ABC	St.Joseph	Basement 1- Back side fire station		13/12/2024	12/12/2025	Refilled OK
276	289	4kg	ABC	St.Joseph	Basement 2- Front side rear fire station		09/12/2024	08/12/2025	Checked OK
277	290	4kg	ABC	St.Joseph	Basement -2nd floor back side fire station		09/12/2024	08/12/2025	Checked OK
278	291	5 kg	BC,DP	Medical collage	Basement floor- electrical room		10/12/2024	09/12/2025	Checked OK
279	292	5 kg	BC,DP	chavara	Store		10/12/2024	09/12/2025	Checked OK
280	293	5kg	BC,DP	chavara	Store		10/12/2024	09/12/2025	Checked OK
281	294	5kg	BC,DP	chavara	Store		11/12/2024	10/12/2025	Checked OK



SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
282	295	5kg	BC,DP	chavara	Store		11/12/2024	10/12/2025	Checked OK
283	296	5kg	BC,DP	chavara	Store		11/12/2024	10/12/2025	Checked OK
284	297	5kg	BC,DP	chavara	Store		13/12/2024	12/12/2025	Refilled OK
285	298	5 kg	ABC MCD	chavara	MRD	2023	11/12/2024	10/12/2025	Checked OK
286	299	5 kg	ABC MCD	chavara	MRD	2023	11/12/2024	10/12/2025	Checked OK
287	300	4kg	ABC	chavara	1st floor- Ward 15		11/12/2024	10/12/2025	Checked OK
288	301	4kg	ABC	chavara	1st floor- Ward 15		11/12/2024	10/12/2025	Checked OK
289	302	4kg	ABC	chavara	1st floor- Ward 12		11/12/2024	10/12/2025	Checked OK
290	303	4kg	ABC	chavara	1st floor- Paediatric ICU		11/12/2024	10/12/2025	Checked OK
291	304	4kg	ABC	chavara	Ground floor- Ward 4		11/12/2024	10/12/2025	Checked OK
292	305	4kg	ABC	chavara	Ground floor- Ward 5		11/12/2024	10/12/2025	Checked OK
293	307	4kg	ABC	chavara	Ground floor- Ward 2 (Nursing station)		11/12/2024	10/12/2025	Checked OK
294	308	4kg	ABC	chavara	second floor		11/12/2024	10/12/2025	Checked OK
295	310	5 kg	ABC MCD	chavara	MRD	2023	11/12/2024	10/12/2025	Checked OK
296	311	5 kg	ABC MCD	chavara	MRD	2023	11/12/2024	10/12/2025	Checked OK
297	312	5 kg	ABC MCD	chavara	MRD	2023	11/12/2024	10/12/2025	Checked OK
298	313	5 kg	ABC MCD	chavara	MRD	2023	11/12/2024	10/12/2025	Checked OK
299	314	5 kg	ABC MCD	chavara	MRD	2023	11/12/2024	10/12/2025	Checked OK
300	315	5 kg	ABC MCD	chavara	MRD	2023	11/12/2024	10/12/2025	Checked OK
301	316	5 kg	ABC MCD	chavara	MRD	2023	11/12/2024	10/12/2025	Checked OK
302	317	5 kg	ABC MCD	chavara	MRD	2023	11/12/2024	10/12/2025	Checked OK
303	318	5 kg	ABC MCD	chavara	MRD	2023	11/12/2024	10/12/2025	Checked OK



SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
304	319	5 kg	ABC MCD	chavara	MRD	2023	11/12/2024	10/12/2025	Checked OK
305	320	4 KG	ABC	chavara	Gastro icu corridor	2022	11/12/2024	10/12/2025	Checked OK
306	321	4 KG	ABC	chavara	first floor OT		11/12/2024	10/12/2025	Checked OK
307	322	5 KG	ABC	chavara	first floor OT		11/12/2024	10/12/2025	Checked OK
308	323	2kg	CO2	chavara	inside blood bank		11/12/2024	10/12/2025	Checked OK
309	324	2 kg	ABC	chavara	Maintenance room		11/12/2024	10/12/2025	Checked OK
310	325	4 KG	ABC	chavara	ground floor ward 3 out side		11/12/2024	10/12/2025	Checked OK
311	326	2kg	CO2	chavara	O2 storage near ip canteen		11/12/2024	10/12/2025	Checked OK
312	328	4kg	ABC	Swanthanam	Swanthanam		12/12/2024	11/12/2025	Checked OK
313	330	4kg	ABC	ip canteen	ip canteen inside		11/12/2024	10/12/2025	Checked OK
314	331	2kg	CO2	ip canteen	ip canteen		11/12/2024	10/12/2025	Checked OK
315	332	9 L	FOAM	ip canteen	ip canteen		11/12/2024	10/12/2025	Checked OK
316	333	2kg	CO2	ip canteen	ip canteen		11/12/2024	10/12/2025	Checked OK
317	334	4kg	ABC	chavara	first floor agape		11/12/2024	10/12/2025	Checked OK
318	335	4kg	ABC	St. joseph	fourth floor back side		09/12/2024	08/12/2025	Checked OK
319	336	2kg	CO2	SH	O2 storage near pump room		09/12/2024	08/12/2025	Checked OK
320	337	2kg	CO2	chavara	O2 storage near laundry		09/12/2024	08/12/2025	Checked OK
321	338	2kg	CO2	St.marys	seventh floor cicu		09/12/2024	08/12/2025	Checked OK
322	339	5 kg	BC,DCP	Matha	hostel		12/12/2024	11/12/2025	Checked OK
323	372	4 KG	ABC	santhanam	ground floor		12/12/2024	11/12/2025	Checked OK
324	384	2kg	CO2	sacred heart	3rd floor Bmt (Near FACP)		10/12/2024	09/12/2024	Checked OK
325	385	2kg	CO2	sacred heart	ground floor		10/12/2024	09/12/2024	Checked OK



SI No.	FE No.	Capacity	Extinguishing Agent	Block	Location	Mfg. Year	Serviced on	Next Service due date	Remarks
326	386	5 kg	BC	Bsc	electric room		10/12/2024	09/12/2024	Checked OK
327	387	4 KG	ABC	anexx	lift machine room		10/12/2024	09/12/2024	Checked OK



Betsy

Dr. BETSY THOMAS
 MD, FRCOG, DNB, MICOG
 PRINCIPAL
 AMALA INSTITUTE OF MEDICAL SCIENCES
 AMALA NAGAR, THRISSUR-680 555